FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

OCATION NAME(S) & ROOM NUMBER(S (6)	n n	RULEVIOLATED (8) PM 305.3	005/Hillsboro High School Hillsboro High School Agricult DESCRIPTION OF THE PROBLEM (9) Ceramic tile cove base has been damaged and tiles are missing allowing for	CAUSE (10)
•		PM 305.3		f
terior	n		unsanitary conditions.	•
		PM 303.2	During heavy rains storm water from teh west side of the building enters through the west doors flooding portions of the building.	i
assroom 105	f	PM 304.16	Exterior door drags on frame preventing proper latching and requiring excessive force to open.	h
roughout	m	PM 304.14	Existing windows have worn beyond normal lifetime (52 years). Windows do not provide adequate protection to interior from the elements or security to the building.	h
roughout	d	185.510	Existing branch circuit wiring insulation throughout the facility has become brittle and damaged creating an unsafe hazard to students and faculty.	h
orage 108	g	185.395.b.4.H	Existing sprinkler riser missing required water flow and tamper switches.	е
echancial 107	g	185.395.c.2	Space missing required smoke/heat detector.	е
assroom 105	g	185.395.d.3	Exterior exit missing required fire alarm manual pull station.	е
ys Toilet 102	е	185.500	Fluorescent light fixture missing required lens.	е
assroom 111 & Break Room 115	d	185.510.a	Receptacle within six feet of water source has no ground fault protection.	е
chanical 107	С	185.720.a	Existing Mechanical Room does not provide the required combustion air for the gas fired water heater.	е
s Garage 113 & 114, Break Room 5, Toilet 116, Storage 117 & Toilet 118	g	185.395.d	Space missing required fire protection and annunciation.	е
is c	esroom 111 & Break Room 115 hanical 107 Garage 113 & 114, Break Room Toilet 116, Storage 117 & Toilet 118	csroom 111 & Break Room 115 d chanical 107 c Garage 113 & 114, Break Room g	ssroom 111 & Break Room 115 d 185.510.a chanical 107 c 185.720.a Garage 113 & 114, Break Room Toilet 116, Storage 117 & Toilet 118	e 185.500 Fluorescent light fixture missing required lens. Receptacle within six feet of water source has no ground fault protection. Responsible 107 c 185.720.a Existing Mechanical Room does not provide the required combustion air for the gas fired water heater. Garage 113 & 114, Break Room Toilet 116, Storage 117 & Toilet 118

- 1. **COUNTY CODE/NAME**. Enter the county name and the 3 digit number taken from the *ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.*
- 2. **DISTRICT CODE/NAME**. Enter district name and the 4-digit number taken from the *ISBE Directory of Illinois Public Schools*, *Public School Districts and other Education Units*.
- 3. SITE CODE. Enter the 3-digit number assigned by the Regional Superintendent.
- 4. **FACILITY CODE/NAME**. Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5. **ITEM I.D.** Enter the number to identify the violation found during the inspection.
- 6. LOCATION NAME(S) & ROOM NUMBER(S). Specify the location name(s) and room number(s) where each of the violation(s) is found.
- 7. TYPE. Enter the type code that best describes the problem

a	Stri	ICT.	ıral

d. Electrical

a. Fire Detection

i. School Security

m. Energy Conservation

b. HVAC

e. Lighting

h. Fire Suppression

k. Handicapped Accessibility

n. Other - Specify:

c. Plumbing

f. Means of Egress

i. Asbestos

I. Improper Space Use

- 8. **RULE VIOLATED**. Specify the rule number in the code that is applicable to the facility where the violation is found, as stated in Section 180.60. *Example: Fire alarm systems are not functioning properly specify section 185.395d, section 175.470 or section 918, the applicable rule used when the building was built.*
- 9. DESCRIPTION OF VIOLATION. In a clear and concise manner, describe the violation
- 10. CAUSE. Enter the code that best describes the probable cause of the problem.
 - a. Improper operation or use
 - d. Defective materials or workmanship
 - q. Vandalism

- b. Inadequate maintenance
- e. Required component or system missing
- h. Worn beyond normal lifetime
- c. Defective design
- f. Accidental damage
- i. Other Specify:

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

068/Mont	1. COUNTY CODE/NAME:			2. DISTRICT CODE/NAME:	4. FACILITY CODE/NAME:				
068/Montgomery				0030/Hillsboro CUSD No. 3		Hillsboro High School A			
ITEM I.D.	ACTION I.D.	PRIORITY CODE		SPECIFICATION(S)	QUANTITY	LABOR	ESTIMATED	ESTIMATED	
(5)	(6)	(7)		(8)		(10)	(11)	COST (12)	DATE (13)
1	С	b	Repair broken and missing ceramic tile cove base by installing new replacement tiles to match existing.				1	\$500.00	2008
2	f	b		ade roadway between Ag Building and Gymnasiu ional area drains as required to prevent flooding.	1 LS	2	\$15,000.00	2008	
3	f	а	Repla	ace door and door hardware.		1 LS	2	\$1,500.00	2007
4	f	С		ove exising steel frame single pane windows and ated glass windows.	1,280 SF	2	\$67,200.00	2008	
5	f	b	Repla	ace branch circuit wiring throughout the building.	1 LS	2	\$40,000.00	2008	
6	f	b	Instal	l flow and tamper switches and associated wiring		1 LS	2	\$4,250.00	2008
7	f	b	Instal	I smoke/heat detector and associated wiring.		1 LS	2	\$500.00	2008
8	f	b	Install	I manual pull station and associated wiring.	į	1 LS	2	\$500.00	2008
9	f	b	Provid	de lens for light fixture.		1 EA	2	\$100.00	2008
10	f	b	Repla	ace existing receptacle with GFI receptacle.		1 EA	2	\$200.00	2008
11	f	b	Provid	de duct connections for required combustion air.	1 LS	2	\$1,750.00	2008	
	,								

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a
THIS IS PAGE 1 OF 2 PAGES

FOR	AMENDMENT NUMBER
ROE USE	AMENDMENT DATE
ONLY	AMENDINENT DATE

	TY CODE/NA	ME:		2. DISTRICT CODE/NAME:	3. SITE CODE/NAME: 005/Hillsboro High School		1	ITY CODE/NAME:	
068/Mon				0030/Hillsboro CUSD No. 3		Hillsboro High School Agriculture Building			
ITEM I.D.	ACTION I.D.	PRIORITY CODE		SPECIFICATION(S)		QUANTITY	LABOR	ESTIMATED COST	ESTIMATED
(5)	(6)	(7)		(8)		(10)	(11)	(12)	COMPLETION DATE (13)
12	f	b	Provi	ide fire alarm devices and associated wiring.		15 EA	2	\$11,250.00	2008
					TOTAL			\$142,750.00	
					Contingency (10%) Construction Budget			\$14,275.00 \$157,025.00	
					A/E Fees Amendment Request			\$14,275.00 \$171,300.00	
					Amendment Request			\$171,300.00	

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a
THIS IS PAGE 2 OF 2 PAGES

Recommended Work Items and Estimated Costs

- 1 COUNTY CODE/NAME Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2 DISTRICT CODE/NAME Enter district name and the 4-digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 3 SITE CODE. Enter the 3-digit number assigned by the REGIONAL SUPERINTENDENT.
- 4 FACILITY CODE/NAME Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5 **ITEM I.D.** Enter the number to identify the violation found during the inspection.
- 6 ACTION I.D. Enter the action code that best describes the nature of the proposed work.
 - a. Abandon in place
- b. Remove
- c. Repair

- d. Relocate
- e. Rebuild
- f. Improve
- 7 PRIORITY CODE. Enter the priority that best describes the degree of hazard the problem creates:
 - a. <u>Urgent</u> identifies items that present an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within one year. Examples are structural, egress, fire protection, fire detection.
 - b. Required identifies items that are necessary for a safe environment but present less of an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within five years.
 - c. Recommended identifies items that do not present any immediate hazard to the students and do not reference any specific rule in the code that are applicable to the building as authorized by ILCS 5/17-2.11. These items are not required by code. Examples of recommended items are: energy conservation; security; repair of school sidewalks, playgrounds, parking lots, school bus turnarounds; or accessibility.
- 8 SPECIFICATIONS. Provide a statement to fully describe the nature and scope of the required work.
- 9 UNITS OF MEASURE. Enter the abbreviated designation which indicates the unit of measure upon which the material cost, labor hours, and crew are based. Examples: C.Y.= Cubic Yard; S.F.= Square Foot; L.F.= Linear Feet; Ea.= Each; Opng.= Opening; Gal.= Gallon.
- 10 QUANTITY. Enter the quality of work to be preformed (e.g. square feet to be repaired, cubic yard of earth to move, etc.).
- 11 LABOR CODE. Enter the labor code if the labor to perform the work is to be provided by employees of the Board of Education as normal part of their routine employment.
 - 1. District employees will perform work
 - 2. Work will be performed by contractor(s).
- 12 **ESTIMATED COST.** Specify the cost incurred to design and execute the work, including profit and overhead. After totaling all of the items, add the architects/engineers' fees and contingency fees on separate lines resulting in the total amount requested.
- 13 ESTIMATED COMPLETION DATE. Enter the estimated completion date.

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180,500 a

FOR ROE	AMENDMENT NUMBER
USE ONLY	AMENDMENT DATE

1. COUNTY 068/Montg		DISTRICT COD 030/Hillsboro C			3. SITE CODE/NAME 005/Hillsboro High School	4. FACILITY CODE/NAME: Hillsboro High School Gymna	sium Building	
ITEM I.D. (5)	LOCATION NAME(S) & ROOM I (6)	NUMBER(S)	TYPE (7)	RULEVIOLATED (8)				
1	Storage		а	185.390(I)	Cast-in-place concrete beam which supports conseverely deteriorated with exposed steel reinfolds		b	
2	Entry 120		j	PM 304.16	Exterior doors have continuous geared hinges and prevent the doors from properly latching.	that have been vandalized	g	
3	Classrooms 122, 123, 127, 126	8 & 129	f	PM 305.3	Existing carpeting in classrooms is worn and se creating a dangerous tripping hazard to the occ		h	
4	Toilets 131 & 132		n	PM 305.3	Ceramic floor tile has broken bond with concret	e subfloor.	d	
5	Gymnasium 102		n	185.830/NFPA 101	Occupant Load is not posted.		е	
6	Storage 207 and Stairs 213		n	PM 305.3	Plaster ceilings have been damaged by water in	nfiltration into the building.	f	
7	Band Room 208		n	185.340(c)(2)	Existing operable wall has exceeded its useful I no longer readily available. Wall panels do not close off the band room from the gymnasium to	perate properly and connot	h	
8	Elec. Equip. 034 & Computer L	.ab 127	g	185.395.c.2	Space missing required smoke/heat detector.		е	
9	Boys Locker 011		f	185.570	Existing emergency light has failed and does no emergency lighting.	ot provide the required	h	
10	Meter Room 026		h	185.395.b.1.E	Sprinkler system valves do not have required ta the fire alarm system.	required tamper switches connected to		
11	Showers 009		С	185.710	Existing showers have exceeded their useful life are no longer available and many leaks exist.	etimes. Replacement parts	h	
12	Toilets 131 & 132		b	185.460.a.1	Toilet Room exhaust fans are inoperable and do exhaust.		h	
Form 35-47 ((3/04) (Prescribed by ISBE for local b	ooard use)				THIS IS PAGE _' OF _	PAGES	

FOR ROE	AMENDMENT NUMBER
ONLY	AMENDMENT DATE

068/Montg		2. DISTRICT COI 0030/Hillsboro	DE/NAME CUSD No	i o. 3	3. SITE CODE/NAME 005/Hillsboro High School	4. FACILITY CODE/NAME: Hillsboro High School Gymna	sium Building
ITEM I.D. (5)	LOCATION NAME(S) & ROO (6)	OM NUMBER(S)	TYPE (7)	RULEVIOLATED (8)	DESCRIPTION OF THE P (9)		CAUSE (10)
13	Home Economics 118		b	185.460.c	Commercial range does not have required exh	aust hood.	е
14	Storage 207		g	185.395.c.2	Space heat detector has been damaged and is	s in need of replacement.	f
15	Band Room 208		е	185.500	Fluorescent light fixture missing required lens.		е
Form 35-47 (3/04) (Prescribed by ISBE for lo	cal board use)				THIS IS PAGE 4 OF 4	PAGES

- 1. **COUNTY CODE/NAME**. Enter the county name and the 3 digit number taken from the *ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.*
- 2. **DISTRICT CODE/NAME**. Enter district name and the 4-digit number taken from the *ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.*
- 3. SITE CODE. Enter the 3-digit number assigned by the Regional Superintendent.
- 4. **FACILITY CODE/NAME**. Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5. **ITEM I.D.** Enter the number to identify the violation found during the inspection.
- 6. LOCATION NAME(S) & ROOM NUMBER(S). Specify the location name(s) and room number(s) where each of the violation(s) is found.
- 7. TYPE. Enter the type code that best describes the problem
 - a. Structural
 - d. Electrical
 - a. Fire Detection
 - i. School Security
 - m. Energy Conservation

- b. HVAC
- e. Liahtina
- h. Fire Suppression
- k. Handicapped Accessibility
- n. Other Specify:

- c. Plumbing
- f. Means of Egress
- i. Asbestos
- I. Improper Space Use
- 8. **RULE VIOLATED**. Specify the rule number in the code that is applicable to the facility where the violation is found, as stated in Section 180.60. *Example: Fire alarm systems are not functioning properly specify section 185.395d, section 175.470 or section 918, the applicable rule used when the building was built.*
- 9. DESCRIPTION OF VIOLATION. In a clear and concise manner, describe the violation
- 10. CAUSE. Enter the code that best describes the probable cause of the problem.
 - a. Improper operation or use
 - d. Defective materials or workmanship
 - d. Vandalism

- b. Inadequate maintenance
- e. Required component or system missing
- h. Worn beyond normal lifetime
- c. Defective design
- f. Accidental damage
- i. Other Specify:

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

1. COUNTY CODE/NAME:				2. DISTRICT CODE/NAME:						
				0030/Hillsboro CUSD No. 3		Hillsboro High School Gymnasium Building				
ITEM I.D.	ACTION I.D.	PRIORITY		SPECIFICATION(S))	QUANTITY	LABOR CODE	ESTIMATED COST	ESTIMATED COMPLETION	
(5)	(6)	(7)		(8)		(10)	(11)	(12)	DATE (13)	
1	С	а	Insta	Il permanent shoring to support deteriorated of	concrete beam.	1 LS	2	\$5,000.00	2007	
2	С	b	Repla	ace continuous geared hinges with new contin	nous geared hinges.	5 EA	1	\$1,250.00	2007	
3	f	b	Repla	ace existing carpeting with new carpeting.		450 SY	2	\$11,250.00	2008	
4	f	b	Repla	ace existing ceramic floor tile with new cerami	ic floor tile.	414 SF	2	\$6,210.00	2008	
5	f	b	Instal	ll required Occupant Load signage.	7 EA	1	\$525.00	2008		
6	f	b		air existing plaster ceilings by removing damaç plaster veneer.	600 SF	2	\$5,000.00	2008		
7	f	b		ove existing operable wall panels and install n een Band Room and Gymnasium.	new operable wall partition	360 SF	2	\$31,860.00	2008	
8	f	b	Instal	I smoke/heat detector and associated wiring.		2 EA	2	\$1,000.00	2008	
9	f	b	Repla	ace existing emergency light.		1 EA	1	\$500.00	2008	
10	f	b	Instal	I flow and tamper switches and associated wi	ring.	1 LS	2	\$4,250.00	2008	
11	f	b	Repla	ace shower units.	8 EA	2	\$8,000.00	2008		
12	f	b	Repla	ace exhaust fans and associated connections.	1 LS	2	\$2,000.00	2008		
13	f	b	Provid	de kitchen hood and associated wiring.	1 LS	2	\$20,000.00	2008		

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a
THIS IS PAGE 1 OF 2 PAGES

FOR	AMENDMENT NUMBER
ROE	
USE	AMENDMENT DATE
ONLY	AMENDIVIENT DATE

	TY CODE/NA	ME:		2. DISTRICT CODE/NAM		3. SITE CODE/NAME:		4. FACII	LITY CODE/NAME:	
068/Mon				0030/Hillsboro CUSD No. 3 005/Hillsboro			High School Hillsboro High School Gymr			nasium Building
ITEM I.D. (5)	ACTION I.D. (6)	PRIORITY CODE (7)			SPECIFICATION(S) (8)		QUANTITY	LABOR CODE	ESTIMATED COST	ESTIMATED COMPLETION
(3)	(0)	(1)			(0)		(10)	(11)	(12)	DATE (13)
14	f	b	Repla	ace heat detector.			1 EA	2	\$250.00	2008
15	f	b	Provi	de lens for light fixture.			1 EA	2	\$100.00	2008
						TOTAL			\$99,695.00	
						Contingency (10%) Construction Budget			\$9,969.00 \$109,664.00	
						A/E Fees Amendment Request			\$9,969.00 \$119,633.00	
						. anonament request			φ110,030.00	

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180,500 a
THIS IS PAGE 2 OF 2 PAGES

Recommended Work Items and Estimated Costs

- 1 COUNTY CODE/NAME Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2 DISTRICT CODE/NAME Enter district name and the 4-digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 3 SITE CODE. Enter the 3-digit number assigned by the REGIONAL SUPERINTENDENT.
- 4 FACILITY CODE/NAME Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent,
- 5 ITEM I.D. Enter the number to identify the violation found during the inspection.
- 6 ACTION I.D. Enter the action code that best describes the nature of the proposed work.
 - a. Abandon in place
- b. Remove
- c. Repair

- d. Relocate
- e. Rebuild
- f. Improve
- 7 PRIORITY CODE. Enter the priority that best describes the degree of hazard the problem creates:
 - a. <u>Urgent</u> identifies items that present an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within one year. Examples are structural, egress, fire protection, fire detection.
 - b. Required identifies items that are necessary for a safe environment but present less of an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within five years.
 - c. <u>Recommended</u> identifies items that do not present any immediate hazard to the students and do not reference any specific rule in the code that are applicable to the building as authorized by ILCS 5/17-2.11. These items are not required by code. Examples of recommended items are: energy conservation; security; repair of school sidewalks, playgrounds, parking lots, school bus turnarounds; or accessibility.
- 8 SPECIFICATIONS. Provide a statement to fully describe the nature and scope of the required work.
- 9 **UNITS OF MEASURE.** Enter the abbreviated designation which indicates the unit of measure upon which the material cost, labor hours, and crew are based. Examples: C.Y.= Cubic Yard; S.F.= Square Foot; L.F.= Linear Feet; Ea.= Each; Opng.= Opening; Gal.= Gallon.
- 10 QUANTITY. Enter the quality of work to be preformed (e.g. square feet to be repaired, cubic yard of earth to move, etc.).
- 11 LABOR CODE. Enter the labor code if the labor to perform the work is to be provided by employees of the Board of Education as normal part of their routine employment.
 - 1. District employees will perform work
 - 2. Work will be performed by contractor(s).
- 12 **ESTIMATED COST.** Specify the cost incurred to design and execute the work, including profit and overhead. After totaling all of the items, add the architects/engineers' fees and contingency fees on separate lines resulting in the total amount requested.
- 13 ESTIMATED COMPLETION DATE. Enter the estimated completion date.

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

068/Montgomery 00		2. DISTRICT CODE/NAME 0030/Hillsboro CUSD No. 3			3. SITE CODE/NAME 005/Hillsboro High School	4. FACILITY CODE/NAME: High School Library/Cafeteria	Building
ITEM I.D. (5)	LOCATION NAME(S) & ROC (6)	OM NUMBER(S)	TYPE (7)	RULEVIOLATED (8)	DESCRIPTION OF THE F	PROBLEM	CAUSE (10)
1	Dining Room 101 & Library 107		n	185.830/NFPA 101	Occupant Load is not posted.		е
2	Computer Lab 106		h	185.395(e)(1)	No fire extinguisher in computer lab.	е	
3	Computer Lab 106 & Office	e 108	n	PM 304.14.1	Broken/cracked window glass.	f	
4	Stairs 008		g	185.395.c.2	Space missing required smoke/heat detector.		е
5	Kitchen 012		b	185.460.a.2	A portion of cooking equipment is not located	е	
6	Work Area 111		d	185.510.a	Receptacle within six feet of water source has	no ground fault protection.	e
7	Corridor 115		f	185.570	Existing emergency light has failed and does remergency lighting.	h	
8	Scullery 004		С	185.710	Existing dishwasher missing required indirect	waste connection.	е
9	Dining Room 001		g	185.395.d.3	Exterior exit missing required fire alarm pull st	ation.	е
Form 35-47 (l (3/04) (Prescribed by ISBE for lo	cal board use)				THIS IS PAGE I OF	PAGES

- 1. COUNTY CODE/NAME. Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2. **DISTRICT CODE/NAME**. Enter district name and the 4-digit number taken from the *ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.*
- 3. SITE CODE. Enter the 3-digit number assigned by the Regional Superintendent.
- 4. FACILITY CODE/NAME. Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5. ITEM I.D. Enter the number to identify the violation found during the inspection.
- 6. LOCATION NAME(S) & ROOM NUMBER(S). Specify the location name(s) and room number(s) where each of the violation(s) is found.
- 7. TYPE. Enter the type code that best describes the problem
 - a. Structural
 - d. Electrical
 - g. Fire Detection
 - j. School Security
 - m. Energy Conservation

- b. HVAC
- e. Lightingh. Fire Suppression
- k. Handicapped Accessibility
- n. Other Specify:

- c. Plumbing
- f. Means of Egress
- i. Asbestos
- I. Improper Space Use
- 8. **RULE VIOLATED**. Specify the rule number in the code that is applicable to the facility where the violation is found, as stated in Section 180.60. *Example: Fire alarm systems are not functioning properly specify section 185.395d, section 175.470 or section 918, the applicable rule used when the building was built.*
- 9. DESCRIPTION OF VIOLATION. In a clear and concise manner, describe the violation
- 10. CAUSE. Enter the code that best describes the probable cause of the problem.
 - a. Improper operation or use
 - d. Defective materials or workmanship
 - g. Vandalism

- b. Inadequate maintenance
- e. Required component or system missing
- h. Worn beyond normal lifetime
- c. Defective design
- f. Accidental damage
- i. Other Specify:

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

1. COUNTY CODE/NAME:				2. DISTRICT CODE/NAME: 3. SITE CODE/NAME:			4. FACILITY CODE/NAME:		
068/Montgomery				0030/Hillsboro CUSD No. 3 005/Hillsboro High School			High School Library/Cafeteria Building		
ITEM I.D. (5)	ACTION I.D. (6)	PRIORITY CODE (7)		SPECIFICATION(S) (8)		QUANTITY (10)	LABOR CODE	ESTIMATED COST	ESTIMATED COMPLETION
	- (0)					4 EA	(11)	(12)	DATE (13)
1	f	b	Install required Occupant Load signage.				1	\$300.00	2008
2	f	а	Insta	ll fire extinguisher.		1 EA	1	\$150.00	2007
3	С	b	Repla	ace broken/cracked window glass.		2 EA	2	\$1,275.00	2008
4	f	b	Instal	ll smoke/heat detector and associated wiring.		1 EA	2	\$500.00	2008
5	f	b	Provi	de kitchen hood for cooking equipment.	1 LS	2	\$40,000.00	2008	
6	f	b	Repla	ace existing receptacle with GFI receptacle.	1 EA	2	\$200.00	2008	
7	f	b	Repla	ace existing emergency light.	1 EA	2	\$500.00	2008	
8	f	b	Provi	de indirect waste connection for dishwasher.	1 LS	2	\$2,000.00	2008	
9	f	b	Instal	I manual pull station and associated wiring.		1 EA	2	\$500.00	2008
					TOTAL Contingency (10%) Construction Budget			\$45,425.00 \$4,543.00 \$49,968.00	
_					A/E Fees Amendment Request			\$4,543.00 \$54,511.00	

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a
THIS IS PAGE 1 OF 1 PAGES

Recommended Work Items and Estimated Costs

- 1 COUNTY CODE/NAME Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2 DISTRICT CODE/NAME Enter district name and the 4-digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 3 SITE CODE. Enter the 3-digit number assigned by the REGIONAL SUPERINTENDENT.
- 4 FACILITY CODE/NAME Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5 **ITEM I.D.** Enter the number to identify the violation found during the inspection.
- 6 ACTION I.D. Enter the action code that best describes the nature of the proposed work.
 - a. Abandon in place b. Remove c. Repair d. Relocate e. Rebuild f. Improve
- 7 PRIORITY CODE. Enter the priority that best describes the degree of hazard the problem creates:
 - a. <u>Urgent</u> identifies items that present an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within one year. Examples are structural, egress, fire protection, fire detection.
 - b. Required identifies items that are necessary for a safe environment but present less of an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within five years.
 - c. Recommended identifies items that do not present any immediate hazard to the students and do not reference any specific rule in the code that are applicable to the building as authorized by ILCS 5/17-2.11. These items are not required by code. Examples of recommended items are: energy conservation; security; repair of school sidewalks, playgrounds, parking lots, school bus turnarounds; or accessibility.
- 8 SPECIFICATIONS. Provide a statement to fully describe the nature and scope of the required work.
- 9 **UNITS OF MEASURE.** Enter the abbreviated designation which indicates the unit of measure upon which the material cost, labor hours, and crew are based. Examples: C.Y.= Cubic Yard; S.F.= Square Foot; L.F.= Linear Feet; Ea.= Each; Opng.= Opening; Gal.= Gallon.
- 10 QUANTITY. Enter the quality of work to be preformed (e.g. square feet to be repaired, cubic yard of earth to move, etc.).
- 11 LABOR CODE. Enter the labor code if the labor to perform the work is to be provided by employees of the Board of Education as normal part of their routine employment.
 - 1. District employees will perform work
 - Work will be performed by contractor(s).
- 12 **ESTIMATED COST.** Specify the cost incurred to design and execute the work, including profit and overhead. After totaling all of the items, add the architects/engineers' fees and contingency fees on separate lines resulting in the total amount requested.
- 13 **ESTIMATED COMPLETION DATE.** Enter the estimated completion date.

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180,500 a

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

1. COUNTY CODE/NAME: 2. DISTRICT C 068/Montgomery 0030/Hillsbord		oro CUSD No	e 0. 3	3. SITE CODE/NAME: 005/Hillsboro High School	4. FACILITY CODE/NAME: Hillsboro High School Main B	Building		
ITEM I.D. (5)	LOCATION NAME(S) & ROOM NUMBER(S) TYPE RULEVIOLATED DESCRIPTION OF THE PROBLEM (9)					CAUSE (10)		
1	Exterior Entrance Doors	j	PM 304.16	Exterior doors have continuous geared hinges that have been vandalized and prevent the doors from properly latching.				
2	Storage 004	h	185.395(e)	Computer network equipment requires a fire extinguisher.				
3	Office 020 & Workroom 110	n	185.370(g)(5)	Door closer has been removed from door.				
4	Storage 007A, 004A, 016, 108A, 117A 8 121A	g	185.395.c.2	Space missing required smoke/heat detector.				
5	Toilets 005, 006, 115, 123, 211 & 218	b	185.460.a.1	Toilet Room exhaust fans are inoperable and do not provide the required exhaust.				
6	Corridor 021	f	185.570	Required emergency light is missing.				
7	Corridor 021 & Gymnasium 015	g	185.395.d.3	Exterior exit missing required fire alarm manual pull station.				
8	Passage 117 & 121	f	185.570	Existing emergency light has failed and does not provide required emergency lighting.				
9	Biology Lab 113 & 114	d	185.510.a	Receptacle within six feet of water source has no ground fault protection.				
10	Biology Lab 114 & Chemistry Lab 205	С	185.440.c.6	Science labs with gas fired equipment does not provide required emergency gas shutoffs.				
11	Boiler Room 011	b	185.405	Existing boiler condensation tank outer liner had Patches have been installed but overall system		h		
Form 35-47 ((3/04) (Prescribed by ISBE for local board use)				THIS IS PAGE 1 OF	1 PAGES		

- 1. COUNTY CODE/NAME. Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2. **DISTRICT CODE/NAME**. Enter district name and the 4-digit number taken from the *ISBE Directory of Illinois Public Schools*, *Public School Districts and other Education Units*.
- 3. SITE CODE. Enter the 3-digit number assigned by the Regional Superintendent.
- 4. **FACILITY CODE/NAME**. Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5. ITEM I.D. Enter the number to identify the violation found during the inspection.
- 6. LOCATION NAME(S) & ROOM NUMBER(S). Specify the location name(s) and room number(s) where each of the violation(s) is found.
- 7. TYPE. Enter the type code that best describes the problem
 - a. Structural
 - d. Electrical
 - g. Fire Detection
 - j. School Security
 - m. Energy Conservation

- b. HVAC
- e. Lighting
- h. Fire Suppression
- k. Handicapped Accessibility
- n. Other Specify:

- c. Plumbing
- f. Means of Egress
- i. Asbestos
- I. Improper Space Use
- 8. **RULE VIOLATED**. Specify the rule number in the code that is applicable to the facility where the violation is found, as stated in Section 180.60. *Example: Fire alarm systems are not functioning properly specify section 185.395d, section 175.470 or section 918, the applicable rule used when the building was built.*
- 9. DESCRIPTION OF VIOLATION. In a clear and concise manner, describe the violation
- 10. CAUSE. Enter the code that best describes the probable cause of the problem.
 - a. Improper operation or use
 - d. Defective materials or workmanship
 - g. Vandalism

- b. Inadequate maintenance
- e. Required component or system missing
- h. Worn beyond normal lifetime

- c. Defective design
- f. Accidental damage
- i. Other Specify:

FOR AMENDMENT NUMBER
ROE
USE
ONLY
AMENDMENT DATE

1. COUNTY CODE/NAME:				2. DISTRICT CODE/NAME:	3. SITE CODE/NAME:		4. FACILITY CODE/NAME:		
068/Montgomery				0030/Hillsboro CUSD No. 3 005/Hillsboro High School			Hillsboro High School Main Building		Building
ITEM I.D.	ACTION I.D.	PRIORITY CODE		SPECIFICATION(S)		QUANTITY	LABOR	ESTIMATED	ESTIMATED
(5)	(6)	(7)	(8)				(11)	COST (12)	DATE (13)
1	С	b	Replace continuous geared hinges with new continuous geared hinges.				1	\$2,500.00	2008
2	f	а	Instal	Il fire extinguisher.		1 EA	1	\$150.00	2007
3	f	а	Instal	ll new door closer.		2 EA	1	\$500.00	2007
4	f	b	Instal	ll smoke/heat detector and associated wiring.		6 EA	2	\$3,000.00	2008
5	f	b	Repla	ace exhaust fan and associated connections.	1 LS	2	\$2,000.00	2008	
6	f	b	Instal	ll emergency light and associated wiring.	1 EA	2	\$750.00	2008	
7	f	b	instal	l manual pull station and associated wiring.	1 EA	2	\$1,000.00	2008	
8	f	b	Repla	ace existing emergency light.	2 EA	2	\$1,000.00	2008	
9	f	b	Repla	ace existing receptacle with GFI receptacle.	3 EA	2	\$600.00	2008	
10	f	b	Provid	de emergency gas shutoff switch and associated p	2 EA	2	\$5,000.00	2008	
11	f	b	Repla	ace existing boiler condensation tank.		1 EA	2	\$5,000.00	2008
					TOTAL Contingency (10%) Construction Budget			\$21,500.00 \$2,150.00 \$23,650.00	
					A/E Fees Amendment Request			\$2,150.00 \$25,800.00	

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a
THIS IS PAGE 1 OF 1 PAGES

Recommended Work Items and Estimated Costs

- 1 COUNTY CODE/NAME Enter the county name and the 3 digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 2 DISTRICT CODE/NAME Enter district name and the 4-digit number taken from the ISBE Directory of Illinois Public Schools, Public School Districts and other Education Units.
- 3 SITE CODE. Enter the 3-digit number assigned by the REGIONAL SUPERINTENDENT.
- 4 FACILITY CODE/NAME Enter the name of the building or structure and the 3-digit facility number assigned by the Regional Superintendent.
- 5 **ITEM I.D.** Enter the number to identify the violation found during the inspection.
- 6 ACTION I.D. Enter the action code that best describes the nature of the proposed work.
 - a. Abandon in placeb. Removec. Repaird. Relocatee. Rebuildf. Improve
- 7 PRIORITY CODE. Enter the priority that best describes the degree of hazard the problem creates:
 - a. <u>Urgent</u> identifies items that present an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within one year. Examples are structural, egress, fire protection, fire detection.
 - b. Required identifies items that are necessary for a safe environment but present less of an immediate hazard to the safety of students and reference specific rules in the code that are applicable to the building. These items must be corrected within five years.
 - C. Recommended identifies items that do not present any immediate hazard to the students and do not reference any specific rule in the code that are applicable to the building as authorized by ILCS 5/17-2.11. These items are not required by code. Examples of recommended items are: energy conservation; security; repair of school sidewalks, playgrounds, parking lots, school bus turnarounds; or accessibility.
- 8 SPECIFICATIONS. Provide a statement to fully describe the nature and scope of the required work.
- 9 UNITS OF MEASURE. Enter the abbreviated designation which indicates the unit of measure upon which the material cost, labor hours, and crew are based. Examples: C.Y.= Cubic Yard; S.F.= Square Foot; L.F.= Linear Feet; Ea.= Each; Opng.= Opening; Gal.= Gallon.
- 10 QUANTITY. Enter the quality of work to be preformed (e.g. square feet to be repaired, cubic yard of earth to move, etc.).
- 11 LABOR CODE. Enter the labor code if the labor to perform the work is to be provided by employees of the Board of Education as normal part of their routine employment.
 - 1. District employees will perform work
 - 2. Work will be performed by contractor(s).
- 12 **ESTIMATED COST.** Specify the cost incurred to design and execute the work, including profit and overhead. After totaling all of the items, add the architects/engineers' fees and contingency fees on separate lines resulting in the total amount requested.
- 13 ESTIMATED COMPLETION DATE. Enter the estimated completion date.

Form 35-48 (3/04) (Prescribed by ISBE for local board use)

180.500 a